




Materials and equipment

1. Appropriate size TPS sleeve
2. Hose and torch
3. Propane gas tank, regulator and gauge
4. Standard safety equipment such as gloves, goggles, hard hat, etc.

Installation has to be done according to local government regulations and usual safety precautions.

For proper selection of joint protection materials, see Product Selection Guide or contact your local Sales Engineer.


Installation instruction



1. Before making the weld, slide the TPS over the pipe end, about 12 inches (300 mm) from the weld area.

Note:


Subsequent removal of the release film from the TPS sleeve on the pipe is easier if the release film has been loosened before the sleeve is placed on the pipe.




2. Clean the weld area with a hand or power wire brush to remove rust, dirt, weld splatter, and foreign materials.* Also, clean adjacent pipe coating that will be covered by the sleeve.

***Note:**

Coal tar - remove the outer paper wrap 6 inches (150 mm) adjacent to the cutback to expose coal tar.
Painted coatings - remove the whitewash paint on the surface of coating to be covered by the sleeve.




3. Preheat the joint until hot to the hand approximately 140°F (60°C) minimum.




4. Remove the inner protective release film of the sleeve. Center the sleeve over the preheated joint, allowing a 2-inch (50 mm) overlap on the mill coating.

Note:

Adjust the flame to approximately 20 inches (500 mm), 6 psi regulator setting. The desired flame should be approximately 1/3 blue cone and 2/3 visible yellow.



5. Heat the sleeve, beginning in the center. Start at the bottom and move upward on both sides. Work to one end, then to the other as shrinkage occurs. Keep the torch moving and apply heat evenly around the sleeve until the pattern on the backing has disappeared and the backing has a smooth surface. During shrinkdown occasionally check mastic flow with gloved finger. Wrinkles should disappear automatically.



6. The sleeve is fully recovered when all of the following have occurred:

- There are no cold spots on the sleeve surface.
- The weld-bead profile is visible on the sleeve.
- After the sleeve is cool, mastic flow is evident on both edges.
- The pattern on the backing has disappeared and the backing has a smooth surface.

Berry Plastics warrants that the product conforms to its chemical and physical description and is appropriate for the use stated on the technical data sheet when used in compliance with Berry Plastics written instructions. Since many installation factors are beyond the control of Berry Plastics, the user shall determine the suitability of the products for the intended use and assume all risks and liabilities in connection herewith. Berry Plastics liability is stated in the standard terms and conditions of sale. Berry Plastics makes no other warranty either expressed or implied. All information contained in this technical data sheet is to be used as a guide and is subject to change without notice. This technical data sheet supersedes all previous data sheets on this product.



CORROSION PROTECTION GROUP
www.berrycpg.com

Local Distributor / Representative:

For contact details of local Distributors / Representatives
Please visit www.berrycpg.com.

Headquarters : Berry Plastics Tapes & Coatings Division, Franklin MA, USA

Franklin, MA, USA

Tel: +1 508 918 1714
US Toll Free: +1 800 248 0149
Fax: +1 508 918 1910
CPG@berryplastics.com

Houston, TX, USA

Tel: +1 713 676 0085
US Toll Free: 01 888 676 7202
Fax: +1 713 676 0086
CPGH@berryplastics.com

Tijuana, Mexico

Tel USA +1 858 633 9797
Fax US: +1 858 633 9740
Tel Mexico: +52 664 647 4397
Fax Mexico: +52 664 647 4370
CPGTJ@berryplastics.com

Westerlo, Belgium

Tel. +32 14 722500
Fax +32 14 722570
CPGE@berryplastics.com

Baroda, India

Tel: +91 2667 264721
Fax: +91 2667 264724
CPGIN@berryplastics.com